

| Customer | Project name |
|---|--|
| Elopak Trading AG | Training PLC GE Fanuc Series 90-30 |
| Škoda Auto a.s. | LJU M2 unit service in M13 |
| Škoda Auto a.s. | Service of Flender electronic transmission |
| Škoda Auto a.s. | Servicing of LJU control units |
| Ekoplastik -pet a.s. | Training PLC GE Fanuc Series 90-30 |
| GE Fanuc Automation Europe S.A. | Application training – Height storage facility for Škoda vehicle bodies |
| Svoboda - grafické závody a.s. | Service intervention by software worker |
| Vodovody a kanalizace Mladá Boleslav a.s. | Signalling of pump no. 4 for Koyo |
| Vodovody a kanalizace Mladá Boleslav a.s. | Assembly and connection of UPS for the GE Fanuc control systém |
| Ideal Standard a.s. | Servicing for GE Fanuc systems |
| A+C spol. s r.o. | Repair of the bottling line controls |
| Conti MB s.r.o. | PLC GE Fanuc training |
| Škoda Auto a.s. | LJU component service |
| Škoda Auto a.s. | Information network for fuel pipelines in facility M1 |
| INGOS s.r.o. | GE Fanuc Quickpanel control panel |
| INGOS s.r.o. | GE Fanuc software |
| TRW-Carr s.r.o. | Service of machine for automatic pressing of pin, sensor, board and pyropatron |
| INGOS s.r.o. | Upgrade of Cimplicity |
| Zapletal-Kovo a.s. | Adjustment of connection of fire prevention gates U23-M2 at Škoda Auto a.s. |
| TRW-Carr s.r.o. | Service of control systems |
| Škoda Auto a.s. | ML Aggregate A04 – Automatic recognition of carriers |
| Datrans s.r.o. | Intervention maintenance of shelf storage facility |
| Datrans s.r.o. | Maintenance of EHC conveyor |
| Škoda Auto a.s. | Change of engine coding on inter-object conveyor |
| Fredenhagen GmbH & Co. KG | Adjustment of emergency stop circuit at SK2 |
| Fredenhagen GmbH & Co. KG | Lit parallel signalling at SK2 and EHM |
| Škoda Auto a.s. | Repair of the Baukema seat conveyor |
| DIS-M s.r.o. | Control and setting of parameters for co-generation station at the Neuberk waste water treatment station |
| CNC invest | Diagnostics related to breakdown of manipulator control system and resource replacement |
| Družstevní závody Dražice | Control of the manipulator for pouring of enamel |
| EXTE spol. s r.o. | Optimisation of SW BMS353 – M11B paint shop |
| DTI-ATT GmbH | Adjustment of software for the M2 muffler unit line |
| Škoda Auto a.s. | Service of LJU for the Kvasiny plant |
| Škoda Auto a.s. | Upgrade and technical support of Cimplicity HMI (M1C) |
| Škoda Auto a.s. | Adjustment of TMB technology and Cockpit for visualisation |

Realizované projekty_EN.xls
2001

| Customer | Project name |
|----------------------------|---|
| Fredenhagen GmbH & Co. KG | Software assistance for restoration of adjustment of tables 29HT2 and HT5 |
| PPU Formex | Electrical adjustment of seat conveyor |
| Fredenhagen GmbH & Co. KG | Disconnection and connection of rotating A29DT3 and A29HT2 raising table |
| VDO Česká republika s.r.o. | Adjustment of EHC line in the area behind the robot's workplace |